Carlson Software Inc.
33 East 2nd Street
Maysville, KY 41056

www.carlsonsw.com
Phone: (606) 564-5028
Fax: (606) 564-6422

Direction of Transfer - Computer to Data Collector

C&G DATA COLLECTOR TRANSFER

1. Set your Data Collector Options Type to **SURVCE**
2. Click on the **Settings** button



C&G DATA COLLECTOR TRANSFER - SETTNGS

3. Data Collector should be set to **SURVCE**
4. Ensure that your Port is set to the proper Com Port. This may be defined by a USB-Serial Adapter
5. Click on **Set Recommended**. Then, Click OK.



RETURN TO C&G DATA COLLECTOR TRANSFER

6. Under **Computer Options**: set the File Type with which you have been working.
7. Click on **Browse** to view the files on the Computer



CHOOSE OUTPUT COORDINATE FILE

8. Highlight the file which you wish to transfer to your Data Collector. Then, Click **Open**.



RETURN TO C&G DATA COLLECTOR TRANSFER

9. Click **Transfer.** Before the transfer is complete, you will be asked to confirm the File.



10. When the transfer is complete, you will see the following message. This procedure will convert your C&G .CRD into a Carlson .CRD*



**C&G .CRD files require a .CGI file to work with. Carlson .CRD does not*