Carlson

Supervisor OS Image Install Instructions

1. Attach a USB keyboard and power supply.

2. Power up the Supervisor and connect the DVD drive to a USB slot, insert the recovery disk.

3. Turn power off and back on and press F11.

4. Arrow down to the DVD drive and press the enter key.

5. Type in DOS command "d:" to get to the directory where the recovery command is.

6. Type in "reccf" for the recovery command.

7. When the install is complete the unit with automatically boot up to the "Activation" process.

8. When the program prompts enter the 25 alpha/numeric key found beneath the battery on the left.

Updated 3/19/2012