


In order to import GIS attributes to SurvCE, you must have two files.


SHA.TXT (orTAB) - Contains the field codes

SHA.FEA - Contains the attributes


1. Save your files into the Data directory of your data collector.
2. From the main menu in SurvCE; select Feature Code List.




3. Tap on Load, on the bottom, left-hand corner, to select your GIS attribute file.




4. Change your File format to TAB.



5. Browse to your file. Then, tap the Green checkmark to load the file.



6. Choose "Yes", when prompted by the following message.



7. Your new FCL will be called SHA, and each Field Code will have its appropriate attributes.

