

www.carlsonsw.com Phone: (606) 564-5028 Fax: (606) 564-6422



This is in regards to replacing the Batteries on a Carlson SS900 Base Radio unit that is over 12 to 18 months old and needs new internal Nickel Metal Hydride battery replacements.

You can order two of the 1500 Mah battery packs designed for the Carlson Explorer to install into your Base Radio unit which is done as shown in the Screenshots below.

Qty to Order: 2

Part # 6100.001.000

Description: Carlson Explorer Battery Pack 1500Mah

List Price: **\$75.00** 



Page 1 of 3 Updated 1/18/2010

## Carlson Software Inc.

102 West 2<sup>nd</sup> Street Maysville, KY 41056

## www.carlsonsw.com

Phone: (606) 564-5028 Fax: (606) 564-6422





This document contains confidential and proprietary information that remains the property of Carlson Software Inc.

Page 2 of 3 Updated 1/18/2010

## Carlson Software Inc. 102 West 2<sup>nd</sup> Street

Maysville, KY 41056

www.carlsonsw.com Phone: (606) 564-5028 Fax: (606) 564-6422





This document contains confidential and proprietary information that remains the property of Carlson Software Inc.

Page 3 of 3 Updated 1/18/2010